- Q: 1. OSHA Occupational Safety Health Administration.
- Q: 2. OSHAS Occupational Safety Health Assessment Series.
- Q: 3. ELCB Earth Leakage Circuit Breaker.
- Q: 4. GFCI Ground Fault Circuit Interrupter.
- Q: 5. BS British Standard.
- Q: 6. SWL Safe Working Load.
- Q: 7. ANSI American National Standard Institution.
- **Q: 8. LTI Lost Time Incident.**
- **Q: 9. ASTM American Society Testing Materials.**
- Q: 10. JSA Job Safety Analysis.
- Q: 11. LEL Lower Explosive Limit.
- Q: 12. UEL Upper Explosive Limit.
- **Q: 13. PEL Permissible Explosive Limit.**
- **Q: 14. REL Recommended Explosive Limit.**
- Q: 15. POUND Square Inch (1 Bar = 14.7Psi)
- Q: 16. SEL Short Term Explosive Limit.
- Q: 17. BGT Wet Bulb Glob Temperature.
- **Q:** 18. APR Air Purifying Respirator.
- Q: 19. ASR Air Supplying Respirator.
- Q: 20. SCBA Self Contained Breathing Apparatus.
- Q: 21. ROS Radiation Safety Officer.
- Q: 22. NFPA National Fire Protection Association.
- Q: 23. MSDS Materials Safety Data Sheet.

Q: 24. STARRT – Safety Task and Risk Reduction Talk.

Q: 25. COSHH - Control of Substances Hazards to Health.

Q: 26. CHB – Chemical Hazard Bulletin.

Q: 27. HW – Hot Work. (RED)

Q: 28. CW – Cold Work. (BLUE)

Q: 29. CSE – Confined Space Entry. (GREEN)

Q: 30. ROPS – Roll Over Protective System.

Q: 31. What is the time frame that preliminary written frame shell submitted the event of an accident involving your company employees or damage to Saudi Aramco equipment property?

ANS: 24 hours / 72 hours.

Q: 32. How far a part should material and equipment storage yards are located from permanent or temporary structure.

ANS: 15 Feet.

Q: 33. How should drinking water on S.A job site be dispensed to workers.

ANS: Disposable paper cup.

Q: 34. Where is a safe place to smoke if any when working on a Saudi Aramco project within a S.A. facilities?

ANS: Designate smoking area / shelter.

Q: 35. When is it acceptable to drill hole on a hard hat?

ANS: Not allowed.

Q: 36. When is it acceptable for a worker to paint his hard hat with a specific color to identify his craft or group?

ANS: Not allowed or acceptable.

Q: 37. What is the proper eye wear to have on when using a portable grinder.

ANS: Safety Glass & Face Shield.

Q: 38. What is general PPE items require for all employees working on S.A. project?

ANS: Safety Glass, hard hat, safety Shoes and reflected vest.

Q: 39. What additional PPE must be warn if any, when working at height more then six feet.

ANS: Full body safety harness with lanyard and anchor.

Q: 40. What is the minimum eye protection required when using an oxygen and acetylene cutting torch?

ANS: Protective eye wear with proper filter (Welding Helmet)

Q: 41. What is the proper respiratory protection to be worn to protect yourself against dust inhalation?

ANS: 3 mm cotton mask or dust mask.

Q: 42. What additional PPE is required if any, when spray painting in progress?

ANS: Chemical cartridge respirator.

Q: 43. What is the required safe distance between flammable storage areas and nearest building storing combustibles?

ANS: 15 meters (50 Feet)

Q: 44. What type of container must be used to transport flammable liquids.

ANS: Metal container.

Q: 45. What type of extinguisher should be used to extinguish a fire involving class "C" materials?

ANS: CO2 / dry chemical powder.

Q: 46. What type of extinguisher should be used to extinguish a fire involving class "a" materials?

ANS: Water.

Q: 47. What type of certification is required to operate a motor vehicle on S.A. project?

ANS: S A government driving license.

Q: 48. What is a confined space permit required in an excavation if ever?

ANS: 1.2 meter (4 Feet).

Q: 49. How long is an S. A. work permit normally valid for?

ANS: One shift or end of job.

Q: 50. What is one method of making a deep excavation safe to work?

ANS: Benching, sloping and shoring.

Q: 51. How far should access/exit ladders in an excavation extend above the stepping off point?

ANS: 01 meter (3 Feet)

Q: 52. How far part should ladder in and excavation be placed?

ANS: 7.5 meters (25 Feet).

Q: 53. What is the safe working pressure for acetylene?

ANS: 15 PSI pound square inch.

Q: 54. How fan apart should oxygen cylinder and flammable gas cylinder be stored?

ANS: 6.1 meter or 20 feet.

Q: 55. What is the proper procedure for compressed gas cylinder?

ANS: Store in upright and secured position with protective cap. Do not store at 54c.

Q: 56. What should be used to protect the valve of a compressed gas cylinder when it is not in used?

ANS: Protective Cap.

Q: 57. What is the proper procedure for lighting a cutting torch?

ANS: Striker shell used.

Q: 58. How many men can be on a step ladder at the same time if the ladder has rungs on one side and the step on the other side?

ANS: Only one.

Q: 59. What is the safest method to prevent an extension ladder from moving or falling while it is in use?

ANS: Securely tied off.

Q: 60. What is the main component of standard scaffold guard rail system?

ANS: Top rail, mid rail, toe boards and support up right.

Q: 61. What is the proper method of securing a hammer head on a wood handle?

ANS: Wooden stick.

Q: 62. What is the required voltage for all portable power tools on S.A. construction project?

ANS: 110 volts to 125 volts.

Q: 63. What must be done prior to changing a grinding disk on a portable grinder?

ANS: Switch off (UN plug).

Q: 64. What (p.pe) beside safety glasses should a worker wear while using a jack hammer?

ANS: Face shield or goggles.

Q: 65. Who can certify a worker to use a cartridge operated tools?

ANS: Certified by S.A.

Q: 66. What is required for all 120 volt, single phase 15 to 20 amperes receptacle outlets on construction site that are not permanent wiring system?

ANS: Ground isolation system (GIS) / ground fault circuit interrupter (GFCI).

Q: 67: What safety device must be present on a grinder to protect operator from contact with blade?

ANS: Safety guard.

Q: 68. What is required prior to be use of a contractor crane on all S. A. project?

ANS: S.A. certified crane operator.

Q: 69. What is the one of the four conditions that must be met for an air compressor to be used for breathing air?

ANS: Third party certified S.A recognized testing agent.

Q: 70. What is the procedure to safety transport a load on forklift when the load restricts the operator forward view?

ANS: Reverse drive.

Q: 71. What color should on oxygen cylinder be?

ANS: Green.

Q: 72. Can damage extension cords be used on S.A. project provided that they are properly spliced?

ANS: Not acceptable.

Q: 73. What safety device should be in a place during arc welding operation to prevent injury to nearby workers?

ANS: Proper welding screens.

Q: 74. What is the minimum frequency that a contractor should conduct a (10) minute safety meeting?

ANS: Once a week and daily with safety supervisor.

Q: 75. What topics would you discuss when giving safety orientation to new hired employee?

ANS: Safety rules, PPE, safe system of work, safety induction, traffic, working at height.

Q: 76. What is the color of H2S?

ANS: Colorless.

Q: 77. When is hearing protection needed?

ANS: 85 dba decibel above.\

Q: 78. When can the receiver live the site?

ANS: Replaced by another receiver of qualified delegate.

Q: 79. Is dead man switch necessary in electrical hand tools?

ANS: Yes.

Q: 80. Is any book needed in the office while handling chemical?

ANS: CHB or MSDS.

Q: 81. When is critical lifting plan required, write any three?

ANS: 1. Crane operating around power line. 2. Night time crane lift. 3. All loads of 40 ton above.

Q: 82. At what wind speed crane lifts is not allowed?

ANS: 32km/h.

Q: 83. At what wind speed is crane suspended man basket not allowed?

ANS: Greater then 25km/h.

Q: 84. Is 220 volts electrical equipment is allowed to use S.A premises?

ANS: Not allowed.

Q: 85. Is flash back arrestor required for oxygen and acetylene cylinder regulator?

ANS: Yes.

Q: 86. What are the types of tags, explain?

ANS: RED: do not use. GREEN: allow to use. YELLOW: use with full body harness with lanyard.

Q: 87. What class of supplied air respirator be used for specified hazard operation?

ANS: Grad D.

Q: 88. When H2S alarm heard in what direction will you live the area?

ANS: Up wind or cross wind.

Q: 89. Is it necessary to know the wind direction when alarm is hard.

ANS: Yes.

Q: 90. Heavy equipment allowed to operate with 1.8m of any excavation?

ANS: Should be 2 meter.

Q: 91. What personal are allowed to enter confined space?

ANS: Only authorized person or trained persons.

Q: 92. What is use to measure radiation?

ANS: Collimator.

Q: 93. Name of four WPs used in Aramco and what their specific color?

ANS: Hot work (RED), Cold Work (BLUE), Confined space entry permit (Yellow), Releases of hazards (YELLOW).

Q: 94. Jan, May, Sep, (GREEN). Feb, Jun, Oct, (RED). March, July, Nov, (BLUE). Apr, August, Dec. (YELLOW).

ANS: GRBY

Q: 95. Who is responsible to conduct site inspection prior to up issuance?

ANS: The permit issuer or his designated representative and the receiver.

Q: 96. Seat belt are required?

ANS: All persons inside the vehicle.

Q: 97. If within arms rich of rotating equipment following can be worn.

ANS: None of the above.

Q: 98. What is the source information to check the properties of suspected hazards chemical?

ANS: MSDS.

Q: 99. You can leave a gas cylinder fitting attached even when not in use as long as under a shade?

ANS: Not allowed to expose direct sunlight or expose none possible ignition (Gas Cylinder)

Q: 100. Oxygen cylinder and acetylene cylinder can be stacked together as they empty.

ANS: Not allowed.

Q: 101. Max working pressure of oxygen is?

ANS: 25 PSI.

Q: 102. Acetylene pressure may be?

ANS: 15 PSI.

Q: 103. A device fitted on oxygen and acetylene regulators to prevent flash back is called?

ANS: Flash back arrestor.

Q: 104. This type of ladder cannot be used while on or electrical equipment or conductor.

ANS: Metal.

Q: 105. This equipment should be available within 3m from hot working activities?

ANS: Fire extinguishers.

Q: 106. Oxygen gas cylinder should be kept at least ----- from fuel gases or separated ----- high nor combustible barrier.

ANS: 20 feet and 5 feet.

Q: 107. Slings and crane hooks are allowed to be used in lifting moving gas cylinder?

ANS: Cylinder Bucket.

Q: 108. It is allowed to work or stand under suspended load when the slings capacity more than the weight of load lifted.

ANS: Not at all.

O: 109. It is permissible not provide barricade for lifting operation whey you are in the middle of the desert and nobody is looking? ANS: All lifting activities should be install for barricades. Q: 110. Operating equipment having danger do not operate tag is allowed? ANS: None of the above. O: 111. Climbing or standing on equipment piping valve or unstable surface is approved when? ANS: Not appropriate under any circumstances. Q: 112. Eating sleeping in this area allowed? ANS: Only in designated area. Q: 113. Height required for body belt to be worn? ANS: 6 feet and above. Q: 114. Fill in tagging requirement for scaffold? A – A scaffold shorter than 6m (20ft) shall be signed by scaffold -----? ANS: Scaffolding Supervisor. B – Scaffold shorter than 6m (20ft) special scaffold shall sign by-----? ANS: Scaffold Supervisor. Q: 115. Who is the person allowed erecting scaffold for S. A.? A – Scaffold shorter than 12.2m (40ft) shall be signed by-----? ANS: Trained and qualified erector. B – Special scaffold or scaffolds taller than 12.2m (40ft)-----? ANS: S. A. approved scaffold contractor. Q: 116. What is the color of tag for scaffold that inspected and signed use?

ANS: Green and Yellow.

Q: 117. What color of tag for scaffold that is inspected but is not ready for use?

ANS: None of the above (Red).

Q: 118-A. An approved specialized scaffold erector can build any types of scaffold?

ANS: Yes.

Q: 118-B. A scaffold erector can build scaffold shorter then-----high under the supervision of S.A. certified scaffold supervisor?

ANS: 12.2 meter (40ft).

Q: 119. What is allowed maximum wind speed for crane lifts?

ANS: 32km/h, 20mp/h, 17knots.

Q: 120. A person allowed operating in S.A. project?

ANS: A. S.A certified crane operator. (YES)

- B. Trainees under the direct supervision of qualified trainer. (NO)
- C. Crane maintenance personal and inspector in the performance of duties.

Q: 121. Who allowed to give signals crane operator during lifting operation and what are their categories?

ANS: A. S.A certified rigger - 3 for load up to 10 tons.

- B. S.A certified rigger 2 for load up to 20 tons.
- C. S.A certified rigger –1 can lift all loads and perform critical lift.

Q: 122. Give at least three type that is categorized as critical lift?

ANS: Tandem lift, lifting of loads above 40 tons, night time lifting.

Q: 123. While lifting a load it is necessary to extend out rigger of the crane fully?

ANS: Yes.

Q: 124. Is hot work or cold work permit is required with a confined space entry permit according to the job done?

ANS: Yes.

Q: 125. Is asbestos containing material is nothing hazards?

ANS: Yes.

Q: 126. Is it allowed to stand on the top of the step ladder?

ANS: No.

Q: 127. Is it necessary to secure the boom of the crane while running from one end to another end?

ANS: Yes.

Q: 128. Is a qualified fire watch maintain during welding operation?

ANS: Yes.

Q: 129. Is a second person is necessary guide the operator of the man lift while moving?

ANS: Yes (Flagman)

Q: 130. Dose every heavy equipment should have and audible back up alarm?

ANS: Yes.

Q: 131. Can you relay on your sense of smell to detect H2S?

ANS: No.

Q: 132. Is H2S heaver than air?

ANS: Yes.

Q: 133. What is I D L H?

ANS: Immediately dangerous to life or health.

Q: 134. Is all boom trucks with loads shall be loaded or unloaded by S.A certified rigger?

ANS: Yes.

Q: 135. Sleeping or resting under or near heavy equipment allowed?

ANS: No.

Q: 136. Is necessary place warring sighs near blasting area?

ANS: Yes.

Q: 137. Temperature of hot asphalt shall not exceed------degree Celsius?

ANS: 232c.

Q: 138. Original copy of the permit is maintained by the issuer for how many month?

ANS: 3 Months.

Q: 139. What situation can cancel the work permit?

ANS: Any unscheduled work stoppage of emergency condition.

Q: 140. Who is responsible for the safety of people and equipments on S.A project?

ANS: Issuer and Receiver.

Q: 141. Permit can be issued up to a period of 30 day under what condition?

ANS: No hydrocarbon present by division head approval.

O: 142. Is welding allowed on lines containing greater then 23.5% oxygen?

ANS: No.

Q: 143. What should be placed outside confined space to notify the personal that entry is in progress?

ANS: Sign board or barricade shall be placed.

Q: 144. Who is allowed to enter in a confined space?

ANS: Only trained person.

Q: 145. What should a danger do not operate tag?

ANS: Date, time, organization, name, badge number, contact number, equipment name, signature of the installer.

Q: 146. Who can operate an abrasive blasting and coating equipment?


ANS: Only qualified and S.A certified personal/

Q: 147. IA side loading while crane operation allowed?

ANS: No. Q: 148. Who should inspect slings, fitting shackles prior to use? ANS: S.A certified rigger. Q: 149. What is a maximum voltage allowed for portable electrical hand tools? ANS: From 110 to 125 voltage. Q: 150, What is the colour of nitrogen cylinder? ANS: Blue. Q: 151. What is the colour of argon cylinder? ANS: Gray. Q: 152. What is the colour of acetylene cylinder? ANS: Yellow. Q: 153. All loads exceeding ----- of the rated load capacity of the crane for that specific lift? ANS: 85%. O: 154. All severs with in ----- shall be covered prior to work? **ANS: 23 meter(75ft).** Q: 155. A qualified fire watch shall be maintained during operations and for -----after work. ANS: 30 min. Q: 156. Cutting welding and brazing are not allowed in O2 enriched concentration greater than----? ANS: 23.5%. Q: 157. Welding cable shall be continuo with in ----- of electrode bolds? ANS: 3m (10ft)

Q: 158. Service vehicles and equipment shall not be located close thanfrom the well head of processing equipment?
ANS: 15m (50ft).
Q: 159. Disable two ways radios and telephones rigging up and loading perforating gun unless the gun is at least down hole?
ANS: 152 meter (500ft).
Q: 160. Qualified personal authorized to work on electrical circuits shall be trained in?
ANS: First Aid and basic life support.
Q: 161. When using full body harness with shock absorbing lanyard they shall be properly secured at least above input surface and not be reused after stopping a fall?
ANS: 5,6m (18ft).
Q: 162. Personal fall arrest system shall be used on any fixed ladder that is overand not equipped with?
ANS: 6m (20ft).
Q: 163. If the work isabove the ground its need scaffold or full body harness?
ANS: 1.8m (6ft).
Q: 164. Only qualified personal shall operate elevating work platform are?
ANS: Man lifts hydraulic / scissor telescoping.
Q: 165. Special scaffold or taller thanrequire additional review by S.A consulting services deportment and as approved third party?
ANS: 38m (125ft).
Q: 166. Move all drums inposition using a drum containment pallet, drum rock, basket, or with a drum handling extension?
ANS: Up right.
O: 167. No drum shall be removed bythem between forks?

ANS: Sand witching. Q: 168. All material handling equipment designed to including-----shall be equipped with? ANS: ROPS (roll over protective structure). Q: 169. Personal monitors shall be worn required by local operation procedures in area where H2S concentration has been detected at -----ppm or greater? ANS: 10ppm. O: 170. All personal performing work in areas where H2S concentration have been detected at -----ppm shall were approved respiratory equipment? ANS: 10ppm. Q: 171. No entry shall be allowed in atmosphere of -----? ANS: 100ppm. Q: 172. Never attempt to rescue an H2S victim without proper respiratory protection in the form of -----? ANS: Self contained breathing apparatus (SCBA). Q: 173. What is odder threshold? ANS: Similar to rotten eggs its limits are on 0.10ppm. Q: 174. Eye irritation and threshold limit value (TLV) limit average TWA-----ppm? ANS: 10ppm. Q: 175. Strong odor and pulmonary irritation begins-----? ANS: 25ppm. Q: 176. Serer conjunctivitis with prolong exposure-----? ANS: 50ppm. O: 177. Sever eye irritation and coughing and loss of sense of smell in 1 minute to 5 IDLH-----?




Q: 188. Never go outside the ship rail unless authorized by the person in charge?
ANS: Yes.
Q: 189. In the event that a person fall in the water immediately shoutassist in the rescue as directed by the person in charge?
ANS: Man over board.
Q: 190. Personal baskets shall not be permitted to transfer personal when the wind speed is?
ANS: 25km/h (14knot).
Q: 191. In case of eye or skin contact promptly flush affected areas with clean water for prolong periodminutes?
ANS: 15min.
Q: 192. Position (lower) hydraulic crane booms and secure hood while traveling?
ANS:
Q: 193. Has regulators shall be turn off and hoses bled off at the end of shift or task?
ANS: Yes.
Q: 194. Only strikers shall be used to light a torch, never light a torch with match or lighter?
ANS: Yes.
Q: 195. Acetylene cylinder in use shall have a handle or valve wrench in place at all times?
ANS: Yes.
Q: 196. Shakles and other connecting devices shall be completely closed?
ANS: Yes.
Q: 197. Drivers shall perform adegree walk around before getting in to the vehicle?

ANS: 360 degree. Q: 198. Drivers shall report all vehicles collision and moving violation immediately no matter how miner? ANS: Yes. Q: 199. Follow proper guidelines for check loading and unloading pyramid or stripped loads? ANS: Yes. Q: 200. Forklifts shall not be used beyond their rated load? ANS: Yes. Q: 201. Forks shall not be left in up position while forklift is unattended? ANS: Yes. Q: 202. A verification of minimum wall thickness and pipe condition shall be conducted welding on wall thickness less than ------ shall nor be allowed? ANS: 0.6cm (0.25inch). O: 203. SCBA equipment shall not be used at depth greater than -----? ANS: 45 meter (150 feet). O: 204. A diving supervisor is required when three or more divers go deeper than -------? ANS: 30 meter (100 feet). Q: 205. A recompression chamber shall be on site for all drivers below? ANS: 18.5m (60ft). Q: 206. All divers shall posses a fit medical certificate not more than how many months?

ANS: 12 months.

Q: 207. Barriers and warning signs shall be established at boundary for safe operation and storage?



ANS: % to slope or 53 degree.	
Q: 219. Stable rock is?	•

ANS: 90 degree or vertical.

Q: 220. Who can certify cartridge operated tools?

ANS: Manufacturing.